

Menu

HISTORY FILE MAP for year 2004

REALTIME


PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK

034.02:00-02:08: 8m realtime 1024bps data lost due to TPL4 failure at DSS 54. System restarted with TLP5, telemetry restored. DR M102267 refers.

036.18:38-18:52: 14m realtime 1024bps data lost due to long 1-way to 2-way transition at DSS34. DR# C103308 refers.



039.16:09-19:06: 2h 57m realtime outage during Jupiter Distant Operations w/ DSU off. Station not available for downlink during this